



Emergency Levee Repairs

Location

River: Sacramento

Site Identification #:
20051230-039-012
(River Mile 15.3)

Latitude/Longitude:
38.172100/-121.646600

Nearest Impact Area:
Brannan-Andrus Island

County: Sacramento

Bank: Left

Type of Damage

Bank scour

Total Length of Repair


260 feet (approximate)

Repair Type

Rock fill, rock-soil mix,
rock slope protection

Lead Agency

Brannan-Andrus Levee
Maintenance District



For further information,
please contact:

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www.levees.water.ca.gov

